Time Line for Revision of Computer Monitor Specification

	Q2 - 2002	Q3 – 2002	Q4 – 2002	Q1 – 2003	Q2 - 2003	Q3 - 2003	Q4 – 2003	Q1 – 2004
	(April – June)	(July - Sept.)	(Oct. – Dec.)	(Jan. – March)	(April – June)	(July – Sept.)	(Oct. – Dec.)	(Jan. – March)
EPA to distribute first draft of	` .	(July – Sept.)	(Oct. – Dec.)	(Jan. – Iviaich)	(April – Julie)	(July – Sept.)	(Oct. – Dec.)	(Jan. – Iviaich)
specification to industry and other	♦							
stakeholders								
EPA to meet with industry in San								
Francisco to discuss first draft of	♦							
specification								
EPA to meet with EU								
representatives in Nice, France to								
present and discuss draft monitor	_							
specification								
EU to send comments to EPA and		>						
EPA to review them								
EPA to work with interested								
manufacturers to refine test								
methodology								
EPA to work with ITI and interested								
manufacturers on product labeling								
ideas and other aspects of								
Partnership Agreement								
Industry to evaluate new test								
methodology and if possible, meter								
current models based on new test								
methodology								
Final day for industry to submit					A			
evaluations of new test methodology					•			
to EPA								
EPA to analyze data and prepare								
Draft 2 of the specification								
EPA to distribute second Draft of					_			
specification to industry and other					•			
stakeholders								
EPA to hold industry meeting to					_			
gather feedback on second Draft					•			
specification								
EPA to prepare final specification								
EPA to distribute final specification					_			
to industry and other stakeholders						*		
EPA to work with industry to								
identify potential venues to								
announce/promote new								
specification. Prepare								
announcement, etc.							_	
Interested manufacturers sign								
Partnership Agreement								
Tentative effective date of								•
specification								·